



**INTERNATIONAL STANDARD ISO 10295-2:2009**  
**TECHNICAL CORRIGENDUM 1**

Published 2009-04-01

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

**Fire tests for building elements and components — Fire testing  
of service installations —**

**Part 2:  
Linear joint (gap) seals**

**TECHNICAL CORRIGENDUM 1**

*Essais au feu pour les éléments et composants de bâtiment — Essai au feu des installations de service —  
Partie 2: Joints d'étanchéité pour interstices linéaires*

*RECTIFICATIF TECHNIQUE 1*

Technical Corrigendum 1 to ISO 10295-2:2009 was prepared by Technical Committee ISO/TC 92, *Fire safety*, Subcommittee SC 2, *Fire containment*.

---

*Page 6, 7.2.3:*

Replace “T” with “ $l_2$ ”.

*Page 6, 7.2.4:*

Replace “T” with “ $l_2$ ”.

*Page 9, 8.1.2.4.4:*

Delete “See Figure 4.”

*Page 11, 10.2.2:*

Delete “See Figure 4.”

---

**ICS 13.220.50; 91.140.01**

**Ref. No. ISO 10295-2:2009/Cor.1:2009(E)**

**Pour plus d'infos, merci de nous contacter.**

**Association Sénégalaise de Normalisation**

4 Avenue Jean Jaurès, Immeuble El Hadj Omar DIA, 6 ème Etage  
Dakar - SENEGAL

**Tel: +221 33 829 58 25**

**Email: [asn@asn.sn](mailto:asn@asn.sn)**