



INTERNATIONAL STANDARD ISO 10295-2:2009
TECHNICAL CORRIGENDUM 1

Published 2009-04-01

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

**Fire tests for building elements and components — Fire testing
of service installations —**

**Part 2:
Linear joint (gap) seals**

TECHNICAL CORRIGENDUM 1

*Essais au feu pour les éléments et composants de bâtiment — Essai au feu des installations de service —
Partie 2: Joints d'étanchéité pour interstices linéaires*

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to ISO 10295-2:2009 was prepared by Technical Committee ISO/TC 92, *Fire safety*, Subcommittee SC 2, *Fire containment*.

Page 6, 7.2.3:

Replace “*T*” with “*l₂*”.

Page 6, 7.2.4:

Replace “*T*” with “*l₂*”.

Page 9, 8.1.2.4.4:

Delete “See Figure 4.”

Page 11, 10.2.2:

Delete “See Figure 4.”

ICS 13.220.50; 91.140.01

Ref. No. ISO 10295-2:2009/Cor.1:2009(E)

Pour plus d'infos, merci de nous contacter.

Association Sénégalaise de Normalisation

4 Avenue Jean Jaurès, Immeuble El Hadj Omar DIA, 6 ème Etage
Dakar - SENEGAL

Tel: +221 33 829 58 25

Email: asn@asn.sn