



INTERNATIONAL STANDARD ISO 13476:1997 TECHNICAL CORRIGENDUM 1

Published 1999-04-01

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

Road vehicles — Ignition coils — Electrical characteristics and test methods

TECHNICAL CORRIGENDUM 1

Véhicules routiers — Bobines d'allumage — Caractéristiques électriques et méthodes d'essai

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to International Standard ISO 13476:1997 was prepared by Technical Committee ISO/TC 22, *Road vehicles*, Subcommittee SC 1, *Ignition equipment*.

Page 6, subclause 4.7.3

In the second sentence, replace “(0,00 5 %/ $V_{\max}$)” with “(0,000 5 %/ $V_{\max}$)”.

Page 7, subclause 5.3

In the formula for the primary current reference time (t_{ref}), replace R_x with R_p .

Pour plus d'infos, merci de nous contacter.

Association Sénégalaise de Normalisation

4 Avenue Jean Jaurès, Immeuble El Hadj Omar DIA, 6 ème Etage
Dakar - SENEGAL

Tel: +221 33 829 58 25

Email: asn@asn.sn